ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 6 | Thanisandra |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W1799 | NA | Tuba Layout Main Road |
| **Segment No.** | **Total Length (m)** | |
| 6/S-W1799/S055546 | 315.23 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 315.23 | 77.628939 | 13.046086 | 77.630188 | 13.044458 | Main Road | End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements To Roads and Drains at Guptha Layout and Surrounding Area Roads in Ward No 06 Thanisandra | 10000000 | 2020-21 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2021 - 2022 | | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | CC Drain Concrete Road | 006-21-000011 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/142/20-21 | 26/11/2020 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 26/11/2020 | 25/11/2023 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Lakshminarayana Reddy | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9740402579 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | suresh devatraj |
| **Date of Inspection** | **Remarks** | |
| 25/03/2021 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition |  | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Sri.S.P.Ranganath | 29/03/2021 | 24/04/2021 | As proposed |
| SE | Vijay Kumar Haridas | 26/03/2021 | 24/04/2021 | Forwarded |
| EE | Mohan Das H T | 26/03/2021 | 24/04/2021 | Approved |
| AEE | B S Sridhar | 25/03/2021 | 24/04/2021 | Approved |
| AE | Suresh Devatraj | 25/03/2021 | 24/04/2021 | Mob Verification Done |
| AE | Suresh Devatraj | 25/03/2021 | 24/04/2021 | Mob Verification |

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 6 | Thanisandra |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W1823, W1190, W1194, W1186, W1180, W1178, W1817, W | 6th Crs, NA, 7th Crs | Rasool Sab Layout Cross Roads |
| **Segment No.** | **Total Length (m)** | |
| 6/C-W1823/S060259 | 436.40 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 30.68 | 77.631436 | 13.044654 | 77.631710 | 13.044584 | main Road | End |
| 2 | 128.35 | 77.631286 | 13.044252 | 77.631484 | 13.045380 | Main Road | End |
| 3 | 108.10 | 77.631334 | 13.045414 | 77.631055 | 13.044476 | Main Road | End |
| 4 | 169.27 | 77.630940 | 13.045524 | 77.630484 | 13.044061 | main Road | End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements To Roads and Drains at Guptha Layout and Surrounding Area Roads in Ward No 06 Thanisandra | 10000000 | 2020-21 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2021 - 2022 | | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Concrete Road CC Drain | 006-21-000011 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/142/20-21 | 26/11/2020 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 26/11/2020 | 25/11/2023 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Lakshminarayana Reddy | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9740402579 | | |



AE

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | suredh devatraj |

| Date of Inspection | Remarks |
|---|---|
| 25/03/2021 | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Sri.S.P.Ranganath | 29/03/2021 | 24/04/2021 | As proposed |
| SE | Vijay Kumar Haridas | 26/03/2021 | 24/04/2021 | Forwarded |
| EE | Mohan Das H T | 26/03/2021 | 24/04/2021 | Approved |
| AEE | B S Sridhar | 25/03/2021 | 24/04/2021 | Approved |
| AE | Suresh Devatraj | 25/03/2021 | 24/04/2021 | Mob Verification Done |
| AE | Suresh Devatraj | 25/03/2021 | 24/04/2021 | For Mob Verification |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1823, W1190, W1194, W1186,